

A
—
B
—
C
—
D
—
E
—
F

B — C — D — E — F



Wiring Diagram



STEP	A	B	C	D
1	+	+	-	-
3	-	+	+	-
4	-	-	+	+
6	+	-	-	+

Clockwise view from mouting side

[illegible]